IN THE LUNG ED STATES PATENT AND TRADEMARK OFFICE

U.S. Patent No.: 6,936,164 B2

Serial No.

: 10/698,447

Filed

: November 3, 2003

FFB 0.6 2006

Certificate

Issued

: August 30, 2005

of Correction

For

: ROTARY DRUM RAINHEAD

PETITION FOR CERTIFICATE OF CORRECTION PURSUANT TO 37 C.F.R. § 1.322 OR § 1.323

Assistant Commissioner for Patents Washington, D. C. 20231

Sir:

Applicants hereby request that the above-identified U.S. patent be corrected in accordance with the attached Certificate of Correction.

I. <u>C.F.R. § 1.322</u>

The mistake(s) were incurred through the fault of the Patent and Trademark Office and are clearly disclosed in the records of the Office. Therefore, no fee is due.

II. <u>C.F.R. § 1.323</u>

At least some of the mistakes was/were made by the applicant. Therefore, a check in the amount of \$100.00 in payment of the fee set forth in 37 C.F.R. § 1.20(a) is enclosed herewith.

Enclosed herewith is a Form PTO-1050 (in duplicate) listing errors that have been found in the above-identified patent. The error(s) are of a clerical or typographical nature or of minor character and were made in good faith. The requested correction(s) do not constitute new matter or require reexamination.

5 2006

Ш. Accordingly, patentees and their assignee respectfully request that the Patent and Trademark Office issue a Certificate of Correction pursuant to 37 C.F.R. § 1.322 or § 1.323, respectively.

Respectfully submitted,

John R. Moses, Reg. No. 24,983 Attorney for Applicants

MILLEN, WHITE, ZELANO & BRANIGAN, P.C. Arlington Courthouse Plaza 1 2200 Clarendon Blvd. Suite 1400 Arlington, Virginia 22201 Telephone: (703) 243-6333 Facsimile: (703) 243-6410

Attorney Docket No.: CULLE-0012

Date: February 1, 2006

JRM:at

PTO/SB/ 44 (08-00)
Approved for use through 09/30/2000. OMB 0651-0033
U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO: 6,936,164B2

DATED: August 30, 2005

1

INVENTOR(S): Rodney George WADE

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

On the front page, (76) Inventor: lines 1-3, reads "Wade, 148 Wongawallen Drive, Upper Coomera, Queensland, 4210 (AU)" should read -- Wade, Upper Coomera, Queensland (AU) --

Column 4, line 12, reads "drum, the" should read -- drum, and the --

Column 4, line 15, reads "drum rotate." should read -- drum to rotate. --

Column 4, line 35, reads "discharge chute" should read -- discharge chute is --

MAILING ADDRESS OF SENDER:

Millen, White, Zelano & Branigan P.C 2200 Clarendon Boulevard Suite 1400 Arlington, VA 22201

PATENT NO. 6,936,164

No. of additional copies



Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.

FER 62006